



## GENUINE MOTOR PARTS AND MOTOR ACCESSORIES BULLETIN

P&A NO. 692

DATE: 02/22/2001



### Updated Screamin' Eagle XL Cams with High Contact Ratio Drive Gear

#### Purpose

This bulletin is to inform you that the Screamin' Eagle XL Performance and Bolt-In Cams are now available with a High Contact Ratio Drive Gear.

#### Background

XL vehicles started using High Contact Ratio Drive Gears in model year 2000. The gears were used to help reduce engine noise. The XXXXX-91 Screamin' Eagle Performance and Bolt-in Cams originally worked in 2000 and later engines only if the pinion gear was changed back to the pre-2000 gear. The older pinion gears are no longer available so this change can no longer be made. These are the part numbers involved: 25647-91A, 25649-91, and 25648-91.

#### Updated 00'-Later Offerings

We have updated the cam gears for 2000 – later XL models and developed new kits. The cams and cam kit listed below now have the High Contact Ratio Drive Gear that will work with 2000 and later pinion gears:

The numbers below will fit on all 2000 and later XL's:

<b>Part #</b>	<b>Description</b>
25647-01 (New)	High Performance XL Cam Kit (Contains Cams and Springs)
25649-01 (New)	High Performance XL Cam Set (Contains Cams only)
25648-01 (New)	XL Bolt-In Cams (Contains Cams only)

#### '99-Earlier Offerings

The numbers below will fit on all 1991 – 1999 XL's and will continue to be offered in the product line:

25647-91A	High Performance XL Cam Kit (Contains Cams and Springs)
25649-91	High Performance XL Cam Set (Contains Cams)
25648-91	XL Bolt-In Cams (Contains Cams only)

Note: For '91-'99 XL's, pinion gear in engine should be reused.

#### Questions

Please contact your SPOC representative with any questions.